


Electric Screw Driver PIU-KZ-6 Exploded drawing



No.	Part name	Qt.
1	Insert bit	1
2	Locator	1
3	Ramp-off sleeve	1
4	O-Ring $\phi 16 \times \phi 2.65$	1
5	Self-tapping screw ST5 \times 42	3
6	Gear box	1
7	O-Ring $\phi 31.5 \times \phi 2.65$	1
8	Roller bearing HK1616	1
9	Spindle	1
10	Spring	1
11	Steel ball $\phi 8$	1
12	Roller bearing HK0709	1
13	Gear shaft	1
14	Woodruff key 2.9 \times 10	1
15	Gear	1
16	Circlip for shaft $\phi 8$	1
17	Bearing 607	1
18	Intermediate mass	1
19	Bearing 608	1
20	Rotor	1
21	Wind guard	1
22	Self-tapping screw ST4 \times 45	2
23	Stator	1
24	Bearing 607	1
25	Bearing cover	1
26	House	1

No.	Part name	Qt.
27	Switch	1
28	Handle cover	1
29	Self-tapping screw ST4 \times 20	3
30	Self-tapping screw ST4 \times 14	2
31	Cable pressboard	1
32	Cable jacket	1
33	Cable	1
34	Brush holder	2
35	Carbon brush	2
36	Lable	1
37	Capacitor 0.22 μ F	1
38	Inductance 0.17mH	1

